
Pachet piese de schimb reparatie masina de spalat vase - ref nr 618014

I.D.: 62919639

Data publicarii 08.11.21 Coduri CPV 50000000-5 42971000-3

Pretul estimativ: 3.075,00 RON - 3.075,00 RON

Descriere: Pachet piese de schimb reparatie masina de spalat vase compus din: -Placa electronica.....buc.1x1780,00lei=1780,00lei -
Termostat.....buc.2x160,00lei=320,00lei -
Electropompa.....buc.1x380,00lei=380,00lei -Capac pompa FIR tip 52B.....buc.1x215,00lei=215,00lei
