

KIT REPARATII MOTOFIERASTRAE

I.D.: 42293590

Data publicarii	20.03.19	Coduri CPV	16800000-3
-----------------	----------	------------	------------

Pretul estimativ: 1.175,78 RON - 1.175,78 RON

Descriere: SINA GHIDAJ 18" 3/8 372 HUSQVARNA # 585950868 - 141.17 lei+TVA/buc - 1 buc LANT 268/372 HUSQVARNA - 68.50 lei+TVA/buc - 1 buc POMPA ULEI 372 HUSQVARNA # 503521303 - 265.21 lei+TVA/buc - 1 buc ULEI UNGERE LANT 10L MAVI - 56.95 lei+TVA/buc - 1 buc ULEI HUSQVARNA - 26.89 lei+TVA/litru - 3 litru LANT 268/372 HUSQVARNA - 68.50 lei+TVA/buc - 1 buc SINA GHIDAJ 18" 3/8 372 HUSQVARNA # 585950868 - 132.77 lei+TVA/buc - 1 buc LANT 268/372 HUSQVARNA - 68.50 lei+TVA/buc - 2 buc FILTRU BENZINA HUSQVARNA # 503443201 - 15.12 lei+TVA/buc - 2 buc PINION ANTRENARE 3/8 268/372 HUSQVARNA - 28.57 lei+TVA/buc - 2 buc PILA ROTUNDA 5.5 OREGON HUSQVARNA - 5.92 lei+TVA/buc - 2 buc PILA LATA HUSQVARNA - 15 lei+TVA/buc - 2 buc SNUR DEMAROR HUSQVARNA # 531003876 - 2.52 lei+TVA/buc - 2 buc TAMBUR DEMAROR 372 HUSQVARNA # 503859601 - 54.62 lei+TVA/buc - 1 buc ARC DEMAROR 372 HUSQVARNA # 503787201 - 33.61 lei+TVA/buc - 1 buc SNUR DEMAROR HUSQVARNA # 531003876 - 2.52 lei+TVA/buc - 1 buc
