
REPARATII POMPE

I.D.: 64591142

Data
publicarii 20.12.21

Coduri CPV

50532100-4

Pretul
estimativ: 1.600,00 RON - 1.600,00 RON

Descriere: REPARATII POMPE SUMERSIBILE, REPARATII POMPA WILO 5 KW : rebobinat ; inlocuire rulmenti ;
inlocuire presutupa ax; lucrari mecanice conexe REPARATII MOTOR REPARATII MOTOR
ACTIONARE VANA AUMA :rebobinat ; inlocuire rulmenti
