
Reparare cazan: inlocuire electrovana defecta

I.D.: 103078023

Data publicarii	18.09.24	Coduri CPV	45259300-0
-----------------	----------	------------	------------

Pretul estimativ:	2.588,33 RON - 2.588,33 RON
-------------------	-----------------------------

Descriere:	Reparare cazan la Sala de Sport: inlocuire electrovana defecta.
------------	---
