
Reparat instalatia sanitara de la sala de sport Gazibara

I.D.: 39138476

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 16.10.19 | Coduri CPV | 50000000-5 |
|-----------------|----------|------------|------------|

Pretul estimativ: 1.156,46 RON - 1.156,46 RON

Descriere: Demolat instalatia sanitara distrusa la toaleta; aprovizionat si montat instalatie sanitara noua; transport materiale, incarcat si descarcat manual, eliberat moloz. Total materiale 182,83 lei, manopera = 739,64 lei; utilaj 75,24 lei, contributie asiguratorie de munca = 16,64 lei; cheltuieli indirecte 142,11 lei, total deviz =1.156,46 lei
