
Reparat instalatia sanitara de la sala de sport Gazibara

I.D.: 39138476

Data publicarii	16.10.19	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.156,46 RON - 1.156,46 RON

Descriere: Demolat instalatia sanitara distrusa la toaleta; aprovizionat si montat instalatie sanitara noua; transport materiale, incarcat si descarcat manual, eliberat moloz. Total materiale 182,83 lei, manopera = 739,64 lei; utilaj 75,24 lei, contributie asiguratorie de munca = 16,64 lei; cheltuieli indirecte 142,11 lei, total deviz =1.156,46 lei
