
Reparatie masina de gatit Arisco

I.D.: 58555083

Data publicarii	02.07.21	Coduri CPV	50000000-5
-----------------	----------	------------	------------

Pretul estimativ: 1.840,00 RON - 1.840,00 RON

Descriere: Reparatie masina de gatit Arisco ce include: sistem flacara de veghe 6x80=480 termocupla 60x2=120; piezzo 95x1=95; cablu bujie 60x1=60; bujie 60x1=60; posta 125x1=125; manopera - 3 ore X 2 tehnicieni X 90lei/h = 540 Deplasare 200kmX1,8/km = 360 TOTAL - 1840 FĂRĂ TVA
