
Inlocuit geam termoizolant spart

I.D.: 43765102

Data publicarii	22.08.19	Coduri CPV	14820000-5
-----------------	----------	------------	------------

Pretul estimativ:	214,59 RON - 214,59 RON
-------------------	-------------------------

Descriere:	Deplasare , constatare si masurare , demontat geam deteriorat si inlocuit cu panel (915x755 mm)
------------	---
