
Verificare, reparatie instalatii de climatizare

I.D.: 71716874

Data publicarii	29.07.22	Coduri CPV	39717200-3
-----------------	----------	------------	------------

Pretul estimativ: 808,97 RON - 808,97 RON

Descriere: eparatie instalatii de climatizare: Verificare presiune instalatie buc 2 Verificare scurgeri freon buc 2 Verificare conexiuni electrice ans 2 Verificare condensator buc 2 Verificare vana cu 3 cai buc 2 Verificare functionare AC rece/cald ans 2 Verificare senzor telecomanda buc 2 Diagnosticare defect UE ans 2
