
Reparatie Mercedes Benz Vito

I.D.: 90313432

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 28.11.23 | Coduri CPV | 50112000-3 50112100-4 |
|-----------------|----------|------------|-----------------------|

| | |
|-------------------|-----------------------------|
| Pretul estimativ: | 3.391,45 RON - 3.391,45 RON |
|-------------------|-----------------------------|

Descriere: CONDUCTA REFRIGERENT INLOCUIRE, VERIFICARE AC CU GAZ SPECIAL, VERIFICARE PLACUTE SI SABOTI SPATE, ASPIRARE REFRIGERENT, INLOCUIRE PLACUTE DE FRANA, INLOCUIRE CANTARE SABOTI SPATE, CONDUCTA DE REFRIGERENT, ORING A/C, AGENT FRIGORIFIC, ULEI COMPRESOR, PLACUTE FRANA SPATE, CANTAR FRANA PARCARE, BOLT, SPRAY CURATITOR
