
Verificare tehnica periodica cazan apa calda, Verificare tehnica periodica tuburi radiante

I.D.: 72951086

Data publicarii	06.09.22	Coduri CPV	50720000-8
-----------------	----------	------------	------------

Pretul estimativ: 2.500,00 RON - 2.500,00 RON

Descriere: Verificare si inspectie cazan apa calda ICI CALDAE tip B23, model REX 20, putere nominala 216 kw, GP: Persoana contact : RSVT-0756335885
