

---

## Servicii de reparatii instalatii termice

I.D.: 103408075

---

Data publicarii	27.09.24	Coduri CPV	45232141-2
-----------------	----------	------------	------------

---

Pretul estimativ: 4.621,85 RON - 4.621,85 RON

---

Descriere: 1. Constatate defectiune pompa circulatie, cazan 290KW. 2. Constatate pierdere presiune instalatie termina interioara 3. Inlocuire pompa recirculare cazan 1buc; 4. Inlocuire robineti izolare coloana alimentare cu energie termica 2buc (accesorii - racord olandez 2", niplu MM - 2buc, garnituri, canepa, pasta etansare, stut filetat 2" - 2buc).

---