
Reparatie Ford Transit

I.D.: 57870912

Data publicarii	11.06.21	Coduri CPV	50112000-3
-----------------	----------	------------	------------

Pretul estimativ:	1.381,30 RON - 1.381,30 RON
-------------------	-----------------------------

Descriere:	Inlocuit sticla oglinda usa stanga, conducta compresor-condensator si supapa EGR Diagnoza Freon
------------	--
