
Servicii verificare, reparare si intretinere centrala termica

I.D.: 51808526

| | | | |
|-----------------|----------|------------|------------|
| Data publicarii | 20.11.20 | Coduri CPV | 45259300-0 |
|-----------------|----------|------------|------------|

| | |
|-------------------|-----------------------------|
| Pretul estimativ: | 1.000,00 RON - 1.000,00 RON |
|-------------------|-----------------------------|

| | |
|------------|---|
| Descriere: | Curatare centrala termica 45 kW .Verificare cos fum. Schimbare supapa de siguranta Inlocuit cos de inox . |
|------------|---|
