
servicii de intretinere si reparatii B76 DOZ

I.D.: 43281590

Data publicarii	24.02.20	Coduri CPV	50112200-5
-----------------	----------	------------	------------

Pretul estimativ: 1.372,19 RON - 1.372,19 RON

Descriere: timbru verde:3 timbru verde:1 og revizie vehicul:1.7 dem/rem discuri frana fata+placute:1.5 test frana:0.3 inlocuit rulment stg fata:1.5 dem tamburi si curatat:2 filtru:1 disc frana:1 set placute frana:1 ulei motor 5w30/1l:3 ulei motor 5w30/4l:1 filtru ulei:1 lichid frana dot4/500ml:1 element filtrant:1 spray:1 col rulment:1
