

Reparatie camera frigorifica

I.D.: 88350531

| | | | |
|-----------------|----------|------------|-----------------------|
| Data publicarii | 16.10.23 | Coduri CPV | 50800000-3 50730000-1 |
|-----------------|----------|------------|-----------------------|

Pretul estimativ: 7.560,00 RON - 7.560,00 RON

Descriere: Reparatie camera frigorifica, 1 buc = 7.560,00 RON
Reparatia include: - Demontat si inlocuit vaporizorul Gunay GND 1.750-2 - Sudura tevi - Vacuumat instalatia - Incarcat cu agent frig R 449A - Reconditionat instalatie electrica - Montat tablou intermediar + contactori comanda motor in vederea functionarii corecte a instalatiei
