
Revizie tehnica pentru auto Dacia Duster nr de inmatriculare B-106-SPI

I.D.: 68204710

Data publicarii	13.04.22	Coduri CPV	34322100-1 09211100-2 42913000-9 42122000-0 34312700-4 34312500-2 34322200-2 34322400-4 39831220-4 34320000-6 50112200-5
-----------------	----------	------------	--

Pretul estimativ:	4.685,07 RON - 4.685,07 RON
-------------------	-----------------------------------

Descriere: Autoritatea contractanta doreste sa achizitioneze servicii de revizie tehnica (inlocuire ulei, filtre, set flanse amortizor, discuri+placute frana, kit distributie, capete de bara, etc.) pentru autoturismul marca Dacia Duster nr de inmatriculare B-106-SPI
