

---

## **Servicii de demontare "Instalatie radiologica de grafie si scopie tip DUODIAGNOST Philips "**

I.D.: 36516854

---

Data publicarii	12.06.19	Coduri CPV	45111300-1
-----------------	----------	------------	------------

---

Termenul limita pentru depunere:	18.06.19
----------------------------------	----------

---

Descriere:	Servicii de demontare "Instalatie radiologica de grafie si scopie tip DUODIAGNOST Philips ".instalatia este casata OBLIGATORIU Firma de service va detine AUTORIZATIE CNCAN de manipulare pentru acest tip de echipament!
------------	---

---