

**„Reparare protectie anticoroziva interior absorber blocul 7" -
SE Isalnita; Cod CPV 45442300-0**

I.D.: 74772074

Data publicarii	02.11.22	Coduri CPV	45442300-0
-----------------	----------	------------	------------

Descriere:	UN SERVICIU CONFORM CAIETULUI DE SARCINI NR. 24186/03.10.2022.
------------	----------------------------------------------------------------
