
Reparatie masina de gatit BERTO'S SPA, model G7TP2F+FG1/

I.D.: 56471485

Data publicarii	29.04.21	Coduri CPV	50800000-3
-----------------	----------	------------	------------

Termenul limita pentru depunere:	06.05.21	Pretul estimativ:	0,01 RON - 840,34 RON
--	----------	-------------------	-----------------------

Descriere:	La pornirea cuptorului butonul nu ramane apasat si cuptorul se opreste (posibil termocupla defecta). Plita masinii de gatit se innegreste si afuma foarte tare(posibil trebuie reglata termocupla).
------------	--
