
Lucrari de reparatie cale rulare decantor radial - Statia de Tratare a Apei Voila.

I.D.: 70611177

Documente participare:

- Caiet de sarcini - Reparatie cale rulare decantor radial - STA VOILA.pdf

Data publicarii	29.06.22	Coduri CPV	45235310-9
-----------------	----------	------------	------------

Termenul limita pentru depunere:	12.07.22	Pretul estimativ:	300.000,00 RON - 300.000,00 RON
--	----------	-------------------	---------------------------------

Descriere: Lucrari de reparatie la calea de rulare a podului raclor - Decantor Radial 1 linie potabila
- STA VOILA , sos. Paltinu (Dj102I), nr 63, Mun. Campina , Jud. Prahova, conform
cerintelor din caietul de sarcini.
