

---

## **servicii de reparatii cenusar(in camera de ardere) cazan Vigas 80**

I.D.: 44294183

---

Data publicarii	23.10.19	Coduri CPV	45259300-0 71630000-3
-----------------	----------	------------	-----------------------

---

Pretul estimativ: 3.200,00 RON - 3.200,00 RON

---

Descriere: -achizitie si inlocuire cenusar (din camera de ardere) - achizirie caramida refractara P4 si Ciment refractara. -montaj cenusar si captusit cu caramida refractara si ciment -probe repunere in functiune cazan

---