

Reparatie pompa

I.D.: 87778156

Data publicarii	04.10.23	Coduri CPV	50511000-0
-----------------	----------	------------	------------

Pretul estimativ:	3.822,76 RON - 3.822,76 RON
-------------------	-----------------------------

Descriere: Constatare, verificare pompa circulatie Wilo, corp dublu
Reparatie - set rulmenti motor electric - 2 ans etansare mecanica - 2 ans Manteriale aditionaLE - GARNITURI, ORINGURI
Manopera reparatie
