
REPARATIE HYUNDAI TUCSON

I.D.: 50386381

Data
publicarii 05.10.20

Coduri CPV

50110000-9

Pretul
estimativ: 300,24 RON - 300,24 RON

Descriere: D/R CARCASA FILTRU AER D/R TUBULATURA SUPRAALIMENTARE D/R TUBULATURA ADMISIE
VERIFICAT NEETANSIETATI INSTALATIE RACIRE INLOCUIT TUBULATURA INSTALATIE RACIRE.
Garantie 12 luni
