



Reparatie instalatie sanitara la Bazinul Olimpic

I.D.: 64059827

Data publicarii	10.12.21	Coduri CPV	45332000-3
-----------------	----------	------------	------------

Pretul estimativ: 3.981,88 RON - 3.981,88 RON

Descriere: Instalatia sanitara de la bazinul olimpic este defecta. Pentru reparatia ei se vor folosi urmatoarele materiale: Colier cu diblu 1.1/4" BAYPA 2 buc Cot PP 40x45 2 buc Robinet coltar 1/2"-3/8" Comfort SCHELL 1 buc Robinet masina spalat 1/2"-3/4" Comfort SCHELL 1 buc Robinet sfera 1" MT Giacomini R254X005 5 buc Teava PP 40/ 0.5m 1 buc Teava PP 40/ 2m 1 buc Teu ZN 1" 1 buc Teu zn 1/2 1 buc Niplu zn 1/2 1 buc Robinet serviciu 1/2 2 buc Robinet apa 1 1 buc Reductie alama 1/2-3/8 1 buc Baterii dus 2 buc Baterii lavoar 6 buc Sifon lavoar 1 buc Racord flexibil inox ptr. Baterie lavoar 4 buc Robinet temporizat pisoar 2 buc Flotor rezervor WC 2 buc Rezervor WC 1 buc
