
Reparatie auto VW PASSAT

I.D.: 44081818

Data publicarii	25.09.19	Coduri CPV	50112100-4
Pretul estimativ:	1.928,93 RON - 1.928,93 RON		
Descriere:	Conform deviz:curatitor-2buc,far-2buc,antigel-4buc,radiator racire-1buc,pompa spalator-1buc,manopera		
