

---

## REPARATIE VW

I.D.: 99323985

---

Data publicarii	26.06.24	Coduri CPV	50112000-3
-----------------	----------	------------	------------

---

Pretul estimativ: 1.200,73 RON - 1.200,73 RON

---

Descriere: Verificare generala Plastic bara fata demo si montat Furtun antigel demo si montat Radiator racire demo si montat Agent racire golit si umplut Aerisit sist racire Mat.mici ConductaAP Antigel Apa distilata , conform oferta

---