
Inspectie si reparare sistem de directie autoturism Skoda Fabia - SRCF Galati

I.D.: 40237496

Data publicarii	22.11.19	Coduri CPV	50112200-5 50110000-9
-----------------	----------	------------	-----------------------

Pretul estimativ: 2.312,73 RON - 2.312,73 RON

Descriere: Achizitia serviciului „Inspectie si reparare sistem de directie” la autoturismul Skoda Fabia cuprinde piese de schimb si manopera. Piese de schimb: Burduf planetara lacv, bec H7 longlife, filtru ulei, saiba buson baie ulei, filtru polen, filtru aer, spray unitate clapeta, spray vaselina HHS 2000, Spray degripant, senzor clapeta, tampon CV, mag prof oe vrac 5W-40. Manopera: Verificare generala mecanica, planetara demontat si montat, burduf planetar interior demontat si montat, verificare sistem.
